

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

RECEIVED

JAN 24 1994

DIVISION OF  
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 1993 To (mo./yr.) Dec. 1993
2. DOGM File Number (Mine No): M / 045 / 002
3. Mine Name: Reilly Wendover
4. Mineral(s) Mined (or permitted to mine): Potash
5. Type of mine ☐ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, 1/4, Section , Township , Range  
1/4, 1/4, Section , Township , Range  
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Reilly Wendover
8. Permanent Street Address : P.O. Box 580  
City, State, Zip: Wendover, Utah 84083-0082  
Phone: (801) 665-2241
9. Company Representative (or designated operator):  
Name: Glenn D. Wadsworth  
Title: Plant Manager  
Business Address: P.O. Box 580  
City, State, Zip: Wendover, Utah 84083-0082  
Phone: (801) 665-2241  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 373,770 st.

3. How much **additional acreage** was disturbed during the past year? 200
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Constructed new barrier trench 50,000 yds

Constructed flood control levee 31,290 yds

5. How much acreage was **reclaimed** during the past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

All areas remained active in 1993.

7. What is the **total disturbed acreage** at years end? 235 Acres

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

The mine is scheduled to remain operational during 1994. All areas for brine collection will continue to be cleaned. All additional areas will continue to be utilized for mining.

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): Glenn D. Wadsworth

Title of Operator: Plant Manager

Signature of Operator: *Glenn D. Wadsworth*


Date: 01/17/94



**REILLY**  
**WENDOVER**



WENDOVER, UTAH

EVAPORATION PONDS  
&  
COLLECTION AREA



LEGEND

SEA. DITCH  
COLLECTION DITCH  
DRAINAGE DITCH  
TRANSFER DITCH  
PUMP - 1000  
PROJECTED PRIMARY POND  
PROJECTED SECONDARY POND  
PROJECTED TERTIARY POND  
PUMPING LEASE  
UTAH STATE LEASE  
POND SYSTEM #2



New barrier trench  
New flood levee

